














Комод К-3


Chest of Drawers K-3

(1001x383x730)




- | | | |
|---------------|--------------|---------------|
| ① 1301x380- 1 | ⑨ 350x90- 1 | ⑰ 640x346- 4 |
| ② 1301x380- 1 | ⑩ 350x90- 1 | ⑱ 1295x346- 2 |
| ③ 668x360- 1 | ⑪ 610x90- 1 | ⑲ 668x360- 1 |
| ④ 668x360- 1 | ⑫ 610x90- 1 | ⑳ 668x360- 1 |
| ⑤ 284x360- 2 | ⑬ 120x350- 3 | ㉑ 661x296- 1 |
| ⑥ 661x296- 1 | ⑭ 120x350- 3 | ㉒ 1268mm- 1 |
| ⑦ 122x696- 1 | ⑮ 120x610- 3 | |
| ⑧ 176x696- 3 | ⑯ 120x610- 3 | |


1 50 x  3,5x16	2 28 x  4x30	3 115 x 	4 36 x 
5 18 x 	6 4 x 	7 4 x  300mm	8 8 x 
9 8 x 	10 10 x 	11 6 x 	12 4 x  N




1




2




3




4




5




6




7



8



9



3x

This diagram shows an exploded perspective view of a rectangular frame assembly. The components are identified by numbered callouts: 1 (corner brackets), 2 (screws), 3 (corner brackets), 4 (corner brackets), 5 (corner brackets), 6 (corner brackets), 7 (side rails), 8 (corner brackets), 9 (corner brackets), 10 (corner brackets), 11 (screws), and 12 (corner brackets). The assembly consists of a rectangular frame with four side rails (7) and four corner brackets (1, 3, 4, 6, 8, 9, 10, 12). The corner brackets are secured with screws (2, 11). The side rails are also secured with screws (2, 11). The exploded view shows the components being assembled into a rectangular frame.

This diagram illustrates the exploded view of a rectangular box assembly. The components are identified by numbered callouts:

- 1**: Screws for the front and side panels.
- 2**: Screws for the bottom panel.
- 5**: Screws for the top panel.
- 7**: A component, possibly a hinge or latch, located on the side panel.
- 8**: The top panel of the box.
- 10**: A component, possibly a hinge or latch, located on the top panel.
- 15**: The bottom panel of the box.
- 16**: The front panel of the box.

The diagram shows the spatial relationship between these parts, with dashed lines indicating the alignment and intended assembly points. A large 'X' is visible in the bottom left corner of the page.

3x